M.V.P. CONSULTANT & ASSOCIATES

Architectural and Structural Design, Approved Valuer for Immovable Assets
Loss assessment, Authorized Structural Engineer, Third Party Quality Monitoring
Survey & Design of Roads and Bridges, Design of H.T. Line & Substations

OFF.- 203, TARA PLACE, NAINITAL ROAD, HALDWANI- 263141 (NAINITAL) U.K.

Ref. No. VOL Myp 01-3389 STRUCTURAL STABILITY CERTIFICATE

Date 3-12-2018

Name of Institution :- Construction for school building of St. Paul Senior Secondary School

Kathgodam distt. Nainital.

Name of society: - St. Paul Senior Secondary School Society Kathgodam NTL.

The school authorities requested to M/s MVP Consultant & Associates for providing structural stability of various blocks in the college campus. These buildings were inspected and examined in detail as Authorised Structural Engineer for Uttarakhand government. The site was inspected on 27/11/2018.

The school campus consist of various buildings. There are 14 blocks of buildings. The blocks are constructed from 1964 till 2005. These blocks are composite construction with load bearing walls / RCC columns and RCC slabs resting on RCC beams. The campus is provided with surface drains and connected to the main municipal drains. The building is being maintained regularly and functioning satisfactorily for the imposed loads.

Followings buildings were inspected and examined for stability aspects:-

- 1. Block A (Class rooms)
- 2. Block B(Class rooms)
- 3. Block C Part a (Class rooms)
- 4. Block C Part b (Class rooms)
- 5. Block D (Class rooms)
- 6. Computer rooms and Class rooms
- 7. Prema Niwas, hostel/residence
- 8. Dining hall
- 9. Kitchen
- 10. Toilet and staff rooms
- 11. Class rooms, Music room, Physics and Biology lab
- 12. Girls hostel and Chemistry lab
- 13. Girls hostel and Administrative block

14. LKG and UKG Class Room

B.Tech, FIE,FIV,F-IA Struct-E, LM-ICI, LM-IRL Authorised Structural Engineer (ASE) Regd. No DOH-UK/G-IASE-13/2015 203, Tarapiece, Naindal Road, Haldwani Oist. - Nainital (Utvrakhand) Mo - 992777471*

From the detailed examinations and inspections the buildings were found to be stable. There were no sign of any settlement or cracks indicating a fairly sound foundation for the structure. The buildings are structurally stable and sound.

This certificate is being issued under the authority by Uttarakhand govt. for Authorized Structural Engineer Registration no. DOH-UK/G-1/ASE-13/2015.

E-mail: consultantmvp@gmail.com Website: www.mvpengineers.com

Contact No.: 05946-222990, 9837048074

GSTIN No.: 05ACCPB0140L2Z9